

CA InterTest Batch 9.1  
CA RS 1603 Service List

Release	Service	Description	Type
9.1	R086910	IN25UTIL ABENDS WITH AN 0C9 PARAMETER USEDSPACEMSG	PTF
	R087177	UNABLE TO SET BP ON WS VARIABLE	PTF
	R087531	BATCH LINK S806 WHEN CAVHLOAD IS NOT IN LINKLIST	PTF
The CA RS 1603 service count for this release is 3			

CA InterTest Batch  
CA RS 1603 Service List for CAMR910

FMID	Service	Description	Type
CAMR910	RO87531	BATCH LINK S806 WHEN CAVHLOAD IS NOT IN LINKLIST	PTF
The CA RS 1603 service count for this FMID is 1			

CA InterTest Batch  
CA RS 1603 Service List for CAVH910

FMID	Service	Description	Type
CAVH910	R086910	IN25UTIL ABENDS WITH AN 0C9 PARAMETER USEDSPACEMSG	PTF
	R087177	UNABLE TO SET BP ON WS VARIABLE	PTF
The CA RS 1603 service count for this FMID is 2			

CA InterTest Batch 9.1  
 CA RS 1603 - PTF RO86910 Details

Release	Service	Details
9.1	RO86910	<p>RO86910 M.C.S. ENTRIES = ++PTF (RO86910)</p> <p>IN25UTIL ABENDS WITH AN 0C9 PARAMETER USEDSPACEMSG</p> <p>PROBLEM DESCRIPTION:            An S0C9 abend occurs while running utility IN25UTIL, which tries to reload a PROTSYM file with INITIALIZE and USEDSPACEMSG parameters in one job step.</p> <p>SYMPTOMS:            An S0C9 abend in IN25UTIL at offset +58BE or a similar one.</p> <p>IMPACT:            Medium. The user is unable to reload program symbolics to the PROTSYM file.</p> <p>CIRCUMVENTION:            Remove the USEDSPACEMSG parameter from the RELOAD step, then create a separate job step to update it. Use the following control cards:            UPDATE,USEDSPACEMSG=</p> <p>PRODUCT(S) AFFECTED:            TESTING TOOLS COMMON SYMBOLIC COMPONENT <span style="float: right;">Release 9.1</span></p> <p>Related Problem:            TFMSYM 374</p> <p>Copyright (C) 2016 CA. All rights reserved. R00029-AVH091-SP1</p> <p>DESC(IN25UTIL ABENDS WITH AN 0C9 PARAMETER USEDSPACEMSG).            ++VER (Z038)            FMID (CAVH910)            PRE ( RO80903 RO82152 )            SUP ( RO83211 TR83211 TR86910 )</p>

CA InterTest Batch 9.1  
CA RS 1603 - PTF RO87177 Details

Release	Service	Details
9.1	RO87177	<p>RO87177 M.C.S. ENTRIES = ++PTF (RO87177)</p> <p>UNABLE TO SET BP ON WS VARIABLE            PROBLEM DESCRIPTION:            An error occurs when trying to set a breakpoint on a working storage variable in Intertest CICS.            SYMPTOMS:            The following error is displayed:            CAIN4716 TASKNUM not found in Symbolic File            CAIN4502 This request disregarded.            CAIN4532 Depress CLEAR for return.            IMPACT:            A breakpoint can't be set at each reference by putting a 'U' next to the variable in working storage.            CIRCUMVENTION:            Place the breakpoints at the desired lines in the program.            PRODUCT(S) AFFECTED:            TESTING TOOLS COMMON SYMBOLIC COMPONENT <span style="float: right;">Release 9.1</span>            Related Problem:            TFMSYM 376            Copyright (C) 2015 CA. All rights reserved. R00031-AVH091-SP1</p> <p>DESC(UNABLE TO SET BP ON WS VARIABLE).            ++VER (Z038)            FMID (CAVH910)            PRE ( RO80903 RO82152 RO83738 )            SUP ( RO82385 RO83360 RO86622 TR78260 TR79576 TR80361            TR82385 TR83360 TR86622 TR87177 )            ++HOLD (RO87177) SYSTEM FMID(CAVH910)            REASON (ACTION ) DATE (15356)            COMMENT (</p> <pre> +-----+   TESTING TOOLS COMMON SYMBOLIC COMPONENT          Release 9.1   +-----+  SEQUENCE   After Apply   +-----+  PURPOSE    Create new member in PROTSYM file.   +-----+  USERS      Intertest CICS users who set breakpoints in the COBOL    AFFECTED   Working Storage area.   +-----+  KNOWLEDGE  Product Administration.    REQUIRED     +-----+  ACCESS     Product Libraries.    REQUIRED     +-----+ ***** * STEPS TO PERFORM * *****           This fix is in the post processing program IN25COB2. In order for you           to set the breakpoint in Working Storage you will need to post process           your COBOL program again using this new version of IN25COB2.           ). </pre>

CA InterTest Batch 9.1  
CA RS 1603 - PTF RO87531 Details

Release	Service	Details
9.1	RO87531	<p>RO87531 M.C.S. ENTRIES = ++PTF (RO87531)</p> <p>BATCH LINK S806 WHEN CAVHLOAD IS NOT IN LINKLIST</p> <p>PROBLEM DESCRIPTION: When one of the CLISTS MR91CLST, MR91CBTS, MR91CDB2 or MR91CIMS is used to access CA InterTest Batch and to convert a JCL for the batch link facility, the resulting JCL produces S806 abend because of missing IN25SAPI module.</p> <p>SYMPTOMS: Abend S806 in the JCL converted for batch link.</p> <p>IMPACT: User is unable to use batch link converted JCLs.</p> <p>CIRCUMVENTION: Concatenate HLQ.CAVHLOAD library to INT1LOAD DD name in the CLIST used to run CA InterTest Batch.</p> <p>PRODUCT(S) AFFECTED: CA-INTERTEST/BATCH-MVS <span style="float: right;">Release 9.1</span></p> <p>Related Problem: INTBAT 998</p> <p>Copyright (C) 2016 CA. All rights reserved. R00030-EJ6091-SP1</p> <p>DESC(BATCH LINK S806 WHEN CAVHLOAD IS NOT IN LINKLIST). ++VER (Z038) FMID (CAMR910) PRE ( RO80909 RO81951 ) SUP ( TR81418 TR81593 TR87531 ) ++HOLD (RO87531) SYSTEM FMID(CAMR910) REASON (ACTION ) DATE (16033) COMMENT (</p> <pre> +-----+            CA-INTERTEST/BATCH-MVS                     Release 9.1            +-----+  SEQUENCE   After Apply                                 +-----+  PURPOSE                 Allow users to use JCLs converted for the batch link                facility without hlq.CAVHLOAD product load library                defined to the linklist.  If hlq.CAVHLOAD product load library is defined                to the linklist then you can ignore this holddata.   +-----+  USERS       AFFECTED                All users who use JCLs converted for the batch link                facility when hlq.CAVHLOAD product load library is                not defined to the linklist.                        +-----+  KNOWLEDGE   REQUIRED                System programmer                                    +-----+  ACCESS      REQUIRED                Access to the necessary system CLIST library.                     Access to the target libraries for CA InterTest Batch.   +-----+ ***** * STEPS TO PERFORM * ***** 1. If, during product configuration, any of the CLISTS MR91CBTS, MR91CDB2, MR91CIMS or MR91CLST were installed, then their copies </pre>

CA InterTest Batch 9.1  
CA RS 1603 - PTF RO87531 Details

Release	Service	Details
		<p>will need to be updated with the new fixed versions.</p> <p>2. Copy the required clist(s); MR91CBTS, MR91CDB2, MR91CIMS and MR91CLST from CAI.CAMRCLS0 to your CLIST library.</p> <p>3. Customize each CLIST as required by your site. Refer to the Customize Clists section of the product install guide for more information.</p> <p>).</p>