

CA Endeavor Software Change Manager 16.0  
CA RS 1603 Service List

| Release  | Service | Description   | Type |
|--|---------|---|------|
| 16.0   | RO87865 | SIGNOUT DATE IS NOT CLEARED AFTER SIGN-IN ACTION          | PTF  |
|  | RO88123 | BSTCOPY MAY NOT ISSUE C1X0511I MESSAGE PRECEDING C1X0500E | PTF  |
|  | RO88372 | EN\$TROPT NOT PRINTED WHEN ENDEVOR INITIALIZATION FAILED  | PTF  |
| The CA RS 1603 service count for this release is 3 |         |   |      |

CA Endeavor Software Change Manager  
CA RS 1603 Service List for CSIQG00

| FMID  | Service | Description   | Type |
|---|---------|---|------|
| CSIQG00   | RO87865 | SIGNOUT DATE IS NOT CLEARED AFTER SIGN-IN ACTION          | PTF  |
|   | RO88123 | BSTCOPY MAY NOT ISSUE CLX0511I MESSAGE PRECEDING CLX0500E | PTF  |
|   | RO88372 | EN\$TROPT NOT PRINTED WHEN ENDEVOR INITIALIZATION FAILED  | PTF  |
| The CA RS 1603 service count for this FMID is 3 |         |   |      |

CA Endeavor Software Change Manager 16.0  
 CA RS 1603 - PTF RO87865 Details

| Release | Service | Details   |
|---------|---------|---|
| 16.0    | RO87865 | <p>RO87865 M.C.S. ENTRIES = ++PTF (RO87865)</p> <p>SIGNOUT DATE IS NOT CLEARED AFTER SIGN-IN ACTION</p> <p>PROBLEM DESCRIPTION:<br/>           New SIGNOUT DATE field in the CSV report output of the LIST ELEMENT request revealed that this field is not cleared after an element is signed in. This is a defect.</p> <p>SYMPTOMS:<br/>           SIGNOUT DATE data field in not cleared after SIGNIN action.</p> <p>IMPACT:<br/>           User's confusion</p> <p>CIRCUMVENTION:<br/>           None</p> <p>PRODUCT(S) AFFECTED:<br/>           CA Endeavor SCM Version 16.0<br/>           CA Endeavor SCM Version 17.0<br/>           CA Endeavor SCM Version 18.0</p> <p>Related Problem:<br/>           ENDBAS 7307</p> <p>Copyright (C) 2016 CA. All rights reserved. R00385-SCM160-SP1</p> <p>DESC(SIGNOUT DATE IS NOT CLEARED AFTER SIGN-IN ACTION).<br/>           ++VER (Z038)<br/>           FMID (CSIQG00)<br/>           PRE ( RO64137 )<br/>           SUP ( TR87865 )</p> |

CA Endeavor Software Change Manager 16.0  
 CA RS 1603 - PTF RO88123 Details

| Release | Service | Details  |
|---------|---------|--|
| 16.0    | RO88123 | <p>RO88123 M.C.S. ENTRIES = ++PTF (RO88123)</p> <p>BSTCOPY MAY NOT ISSUE C1X0511I MESSAGE PRECEDING C1X0500E</p> <p>PROBLEM DESCRIPTION:<br/>           In case of bad syntax is found within the BSTCOPY copy statement, the error message C1X0500E is issued. The informational message C1X0511I containing the line with problematic statement should precede. However in certain situation, when there are more select member statements or more members within one select statement, this information message is not printed in case of bad syntax is found.</p> <p>SYMPTOMS:<br/>           No C1X0511I message with a command with wrong syntax is preceding C1X0500E message.</p> <p>IMPACT:<br/>           User's confusion</p> <p>CIRCUMVENTION:<br/>           None</p> <p>PRODUCT(S) AFFECTED:<br/>           CA Endeavor SCM Version 16.0<br/>           CA Endeavor SCM Version 17.0<br/>           CA Endeavor SCM Version 18.0</p> <p>Related Problem:<br/>           ENDBAS 7315</p> <p>Copyright (C) 2016 CA. All rights reserved. R00387-SCM160-SP1</p> <p>DESC(BSTCOPY MAY NOT ISSUE C1X0511I MESSAGE PRECEDING C1X0500E).<br/>           ++VER (Z038)<br/>           FMID (CSIQG00)<br/>           PRE ( RO69706 RO74068 RO84102 )<br/>           SUP ( RO81544 TR81544 TR88123 )</p> |

CA Endevor Software Change Manager 16.0  
CA RS 1603 - PTF RO88372 Details

| Release | Service | Details   |
|---------|---------|---|
| 16.0    | RO88372 | <p>RO88372 M.C.S. ENTRIES = ++PTF (RO88372)</p> <p>EN\$TROPT NOT PRINTED WHEN ENDEVOR INITIALIZATION FAILED</p> <p>PROBLEM DESCRIPTION:<br/>The Site Options Settings trace (EN\$TROPT) is not printed when the Endevor initialization failed. EN\$TROPT output might often be useful for debugging why the Endevor initialization failed.</p> <p>SYMPTOMS:<br/>The EN\$TROPT DD was coded in the JCL but the Site Options Settings trace is not printed because the Endevor initialization failed.</p> <p>IMPACT:<br/>It can be hard for CA Technical Support personnel to debug why the Endevor initialization failed.</p> <p>CIRCUMVENTION:<br/>None.</p> <p>PRODUCTS AFFECTED:<br/>CA Endevor Software Change Manager, Version 16.0<br/>CA Endevor Software Change Manager, Version 17.0<br/>CA Endevor Software Change Manager, Version 18.0</p> <p>Related Problem:<br/>ENDBAS 7316</p> <p>Copyright (C) 2016 CA. All rights reserved. R00391-SCM160-SP1</p> <p>DESC(EN\$TROPT NOT PRINTED WHEN ENDEVOR INITIALIZATION FAILED).<br/>++VER (Z038)<br/>FMID (CSIQG00)<br/>PRE ( RO63603 RO63917 RO65628 RO67754 RO76090 )<br/>SUP ( RO56373 RO59746 RO67747 TR56373 TR59746 TR67747<br/>TR88253 TR88372 )</p> |