

CA Endeavor Software Change Manager 17.0
CA RS 1603 Service List

Release	Service	Description	Type
17.0	RO83927	SIGNOUT OVERRIDE EMAIL ISSUED INCORRECTLY FOR ALTER	PTF
	RO87866	SIGNOUT DATE IS NOT CLEARED AFTER SIGN-IN ACTION	PTF
	RO88124	BSTCOPY MAY NOT ISSUE C1X0511I MESSAGE PRECEDING C1X0500E	PTF
	RO88260	ENHANCED EN\$TRALC/EN\$TRESI TRACE	PTF
	RO88373	EN\$TROPT NOT PRINTED WHEN ENDEVOR INITIALIZATION FAILED	PTF
The CA RS 1603 service count for this release is 5			

CA Endeavor Software Change Manager
CA RS 1603 Service List for CSIQH00

FMID	Service	Description	Type
CSIQH00	RO83927	SIGNOUT OVERRIDE EMAIL ISSUED INCORRECTLY FOR ALTER	PTF
	RO87866	SIGNOUT DATE IS NOT CLEARED AFTER SIGN-IN ACTION	PTF
	RO88124	BSTCOPY MAY NOT ISSUE C1X0511I MESSAGE PRECEDING C1X0500E	PTF
	RO88260	ENHANCED EN\$TRALC/EN\$TRESI TRACE	PTF
	RO88373	EN\$TROPT NOT PRINTED WHEN ENDEAVOR INITIALIZATION FAILED	PTF
The CA RS 1603 service count for this FMID is 5			

CA Endeavor Software Change Manager 17.0
 CA RS 1603 - PTF RO83927 Details

Release	Service	Details
17.0	RO83927	<p>RO83927 M.C.S. ENTRIES = ++PTF (RO83927)</p> <p>SIGNOUT OVERRIDE EMAIL ISSUED INCORRECTLY FOR ALTER</p> <p>PROBLEM DESCRIPTION: An ALTER action will issue a signout override message if an element is currently signed out to a userid which is different than the userid executing the ALTER action.</p> <p>This is an example of the message the current ALTER action: GIFRM21 has just overridden your signout of element ELM001 on 26JAN2016 at 09:56 while doing the ALTER action.</p> <p>This element was located at: Env : ENV1 System : P7265 Subsystem: P7265 Type : P1234567 Stage : 1</p> <p>The message is misleading because: 1. The ALTER action does not change the signout userid unless REPLACE SIGNOUT USERID is specified. 2. The ALTER may not make any changes due to filtering 3. The ALTER may not make any changes due to the use of the NOUPDATE option.</p> <p>SYMPTOMS: Misleading email message.</p> <p>IMPACT: The email message is misleading</p> <p>CIRCUMVENTION: None.</p> <p>PRODUCT(S) AFFECTED: CA Endeavor SCM Version 17.0 CA Endeavor SCM Version 18.0</p> <p>Related Problem: ENDBAS 7265</p> <p>Copyright (C) 2016 CA. All rights reserved. R00156-SCM170-SP1</p> <p>DESC(SIGNOUT OVERRIDE EMAIL ISSUED INCORRECTLY FOR ALTER). ++VER (Z038) FMID (CSIQH00) PRE (RO71576 RO82472) SUP (RO82540 TR80989 TR82540 TR83927)</p>

CA Endeavor Software Change Manager 17.0
 CA RS 1603 - PTF RO87866 Details

Release	Service	Details
17.0	RO87866	<p>RO87866 M.C.S. ENTRIES = ++PTF (RO87866)</p> <p>SIGNOUT DATE IS NOT CLEARED AFTER SIGN-IN ACTION</p> <p>PROBLEM DESCRIPTION: New SIGNOUT DATE field in the CSV report output of the LIST ELEMENT request revealed that this field is not cleared after an element is signed in. This is a defect.</p> <p>SYMPTOMS: SIGNOUT DATE data field in not cleared after SIGNIN action.</p> <p>IMPACT: User's confusion</p> <p>CIRCUMVENTION: None</p> <p>PRODUCT(S) AFFECTED: CA Endeavor SCM Version 16.0 CA Endeavor SCM Version 17.0 CA Endeavor SCM Version 18.0</p> <p>Related Problem: ENDBAS 7307</p> <p>Copyright (C) 2016 CA. All rights reserved. R00191-SCM170-SP1</p> <p>DESC(SIGNOUT DATE IS NOT CLEARED AFTER SIGN-IN ACTION). ++VER (Z038) FMID (CSIQH00) PRE (RO71576) SUP (TR87866)</p>

CA Endeavor Software Change Manager 17.0
 CA RS 1603 - PTF RO88124 Details

Release	Service	Details						
17.0	RO88124	<p>RO88124 M.C.S. ENTRIES = ++PTF (RO88124)</p> <p>BSTCOPY MAY NOT ISSUE C1X0511I MESSAGE PRECEDING C1X0500E</p> <p>PROBLEM DESCRIPTION: In case of bad syntax is found within the BSTCOPY copy statement, the error message C1X0500E is issued. The informational message C1X0511I containing the line with problematic statement should precede. However in certain situation, when there are more select member statements or more members within one select statement, this information message is not printed in case of bad syntax is found.</p> <p>SYMPTOMS: No C1X0511I message with a command with wrong syntax is preceding C1X0500E message.</p> <p>IMPACT: User's confusion</p> <p>CIRCUMVENTION: None</p> <p>PRODUCT(S) AFFECTED:</p> <table data-bbox="440 709 1377 793"> <tr> <td>CA Endeavor SCM</td> <td>Version 16.0</td> </tr> <tr> <td>CA Endeavor SCM</td> <td>Version 17.0</td> </tr> <tr> <td>CA Endeavor SCM</td> <td>Version 18.0</td> </tr> </table> <p>Related Problem: ENDBAS 7315</p> <p>Copyright (C) 2016 CA. All rights reserved. R00193-SCM170-SP1</p> <p>DESC(BSTCOPY MAY NOT ISSUE C1X0511I MESSAGE PRECEDING C1X0500E). ++VER (Z038) FMID (CSIQH00) PRE (RO75121 RO84103) SUP (RO81545 TR81545 TR88124)</p>	CA Endeavor SCM	Version 16.0	CA Endeavor SCM	Version 17.0	CA Endeavor SCM	Version 18.0
CA Endeavor SCM	Version 16.0							
CA Endeavor SCM	Version 17.0							
CA Endeavor SCM	Version 18.0							

CA Endeavor Software Change Manager 17.0
 CA RS 1603 - PTF RO88260 Details

Release	Service	Details
17.0	RO88260	<p>RO88260 M.C.S. ENTRIES = ++PTF (RO88260)</p> <p>ENHANCED EN\$TRALC/EN\$TRESI TRACE</p> <p>PROBLEM DESCRIPTION:</p> <p>EN\$TRALC and EN\$TRESI traces do not provide information from where allocation (BC1PAL10) and external security (BC1PESSI) were called.</p> <p>SYMPTOMS:</p> <p>Not having information about callers.</p> <p>IMPACT:</p> <p>More difficult to diagnose the problem according to traces.</p> <p>CIRCUMVENTION:</p> <p>None.</p> <p>PRODUCT(S) AFFECTED:</p> <p>CA Endeavor SCM Version 17.0</p> <p>CA Endeavor SCM Version 18.0</p> <p>Related Problem:</p> <p>ENDBAS 7311</p> <p>Copyright (C) 2016 CA. All rights reserved. R00196-SCM170-SP1</p> <p>DESC(ENHANCED EN\$TRALC/EN\$TRESI TRACE).</p> <p>++VER (Z038)</p> <p>FMID (CSIQH00)</p> <p>PRE (RO71392 RO71397 RO71576 RO72200 RO72695 RO74136 RO74692 RO78177 RO80617 RO80640 RO82327 RO84103 RO85998 RO86723)</p> <p>SUP (RO72103 RO75059 TR72103 TR75059 TR88260)</p>

CA Endevor Software Change Manager 17.0
 CA RS 1603 - PTF RO88373 Details

Release	Service	Details
17.0	RO88373	<p>RO88373 M.C.S. ENTRIES = ++PTF (RO88373)</p> <p>EN\$TROPT NOT PRINTED WHEN ENDEVOR INITIALIZATION FAILED</p> <p>PROBLEM DESCRIPTION:</p> <p>The Site Options Settings trace (EN\$TROPT) is not printed when the Endevor initialization failed. EN\$TROPT output might often be useful for debugging why the Endevor initialization failed.</p> <p>SYMPTOMS:</p> <p>The EN\$TROPT DD was coded in the JCL but the Site Options Settings trace is not printed because the Endevor initialization failed.</p> <p>IMPACT:</p> <p>It can be hard for CA Technical Support personnel to debug why the Endevor initialization failed.</p> <p>CIRCUMVENTION:</p> <p>None.</p> <p>PRODUCTS AFFECTED:</p> <p>CA Endevor Software Change Manager, Version 16.0 CA Endevor Software Change Manager, Version 17.0 CA Endevor Software Change Manager, Version 18.0</p> <p>Related Problem:</p> <p>ENDBAS 7316</p> <p>Copyright (C) 2016 CA. All rights reserved. R00198-SCM170-SP1</p> <p>DESC(EN\$TROPT NOT PRINTED WHEN ENDEVOR INITIALIZATION FAILED). ++VER (Z038) FMID (CSIQH00) PRE (RO71576 RO76091) SUP (RO70847 TR70847 TR88258 TR88373)</p>